


City of Detroit  
Department of Recreation Performance Audit  
Exhibit 4 - Kronk Center



Plaster missing from ceiling – possible water damage.



Loose electrical outlet and peeling paint.



City of Detroit  
Department of Recreation Performance Audit  
Exhibit 4 - Kronk Center



Peeling drywall – possible water damage.



Badly rusted and dirty lockers.